

PosiTector® **DPM** Probe Order Guide

Probe Style	DPM	DPMS	DPMA	DPMD
Comparison Chart				
Order Code	PRBDPM	PRBDPMS	PRBDPMA	PRBDPMD
Surface Temperature	•	•	•	
Air Temperature	•	•	•	•
Wet Bulb Temperature*	•	•	•	•
Relative Humidity	•	•	•	•
Dew Point Temperature	•	•	•	•
Surface Temperature minus Dew Point Temperature	•	•	•	
Wind Speed			•	

* Wet Bulb Temperature displayed/recorded on PosiTector Advanced (3) models only


Probe Details

Integral Probe with Cabled Surface Temperature Sensor (DPMS)

- Includes built-in air temperature/humidity sensor and K-type connector
- Magnetic surface temperature sensor with armored cable and locking device to prevent accidental disconnection from the instrument during unattended operation
- Includes magnetic tab to attach the PosiTector body onto steel structures

Easily converts to accept other optional K-type thermocouple sensors including

- (a) hand-held surface temperature sensor
- (b) self-adhering surface temperature sensor
- (c) liquid temperature sensor



DeFelsko®
The Measure of Quality

DeFelsko Corporation 800 Proctor Ave., Ogdensburg, New York 13669-2205 USA
Toll Free 1-800-448-3835 • Tel: +1-315-393-4450 • Fax: +1-315-393-8471
techsale@defelsko.com • www.defelsko.com

© DeFelsko Corporation USA 2017. All Rights Reserved. Technical Data subject to change without notice. • DPMPRB1711


Made in U.S.A.